

## Price list for engine repair services



Service	Price (AED)
Intake manifold gasket replacement	from 350
Valve cover gasket replacement	from 400
Engine mount replacement	from 250
Cylinder head gasket replacement	from 1500
Turbocharger replacement	from 600
Camshaft sensor replacement	from 150
Camshaft seal replacement	from 500
Crankshaft seal replacement	from 500
Crankshaft sensor replacement	from 150
Crankshaft pulley replacement	from 350
Valve stem seal replacement	from 2000
Camshaft replacement	from 1000
Engine protection installation	from 100
Valve adjustment	from 1000
Oil pan gasket replacement	from 500