

Price list for suspension repair services



Service	Price [AED]
Wheel hub bearing replacement	from 150
Hub replacement	from 150
Control arm bushing replacement	from 100
Stabilizer link replacement	from 100
Stabilizer bushing replacement	from 100
Ball joint replacement	from 100
Shock absorber replacement	from 150
Shock absorber mount replacement	from 150
Spring replacement	from 150
Control arm replacement	from 150
Subframe bushing replacement	from 1200
Strut bearing replacement	from 200
Rear beam bushing replacement	from 1200
ABS sensor replacement	from 100
Brake pad replacement	from 100

Service	Price (AED)
Brake hose replacement	from 150
Brake bleeding	from 200
Handbrake adjustment	from 200
Wheel cylinder replacement	from 300
Caliper replacement	from 150
Handbrake cable replacement	from 200
Master brake cylinder replacement	from 200
Brake drum replacement	from 100
Brake pad wear sensor replacement	from 100
Tie rod end replacement	from 100
Tie rod replacement	from 100
Steering rack replacement	from 100
Steering rack boot replacement	from 400
Steering shaft cross joint replacement	from 300
CV joint replacement	from 250
CV boot replacement	from 300
Gear shifter replacement	from 250
Axle bearing replacement	from 250
Center support bearing replacement	from 300
Cardan shaft cross joint replacement	from 450
DSG fluid replacement	from 350
Gearbox oil seal replacement	from 150
Automatic transmission filter replacement	from 300
Driveshaft replacement	from 250
Driveshaft oil seal replacement	from 200